

## Front Side Project Punch List

(List made from final walk-through and owners emails/calls)

- Screen Missing – 728
- Slider's Locking Automatically – 726
- Broken Piece of Siding – East Side of 700 Building
- Slider Handle Loose + Won't Tighten – 654
- Window Furring Weather Strip Comes Out – 626
- Dryer Vent Broken in Carport – 626
- Missing Piece of Artificial White Lumber Under Front Door – 626
- Disconnected Pieces of Metal Tubing Were Discovered in Several Locations – Fire Pro Was Contacted to Remove Them.
- Metal Piping Near Cubby Door Restricts Door From Fully Opening – 660. Fire Pro Was Contacted to Correct Problem.
- Several Unit Owners Reported Having Difficulty Locking the New Windows – **This problem is the result of closing the window with too much power which causes the window lock mechanism to misalign. Solution – Close the Window with Less Force.**

**\* Unless otherwise noted C/W Builders will correct all reported problems.**

**\*\* If you have something that needs to be corrected/fixed as part of the Front Side Renovation, please send an email via the Casa Del Sol Website or call Mann Properties at 410-89-6156.**

**\*\* If you contact Walt Smelter directly at 410-352-3001 or [wasinccwbs@aol.com](mailto:wasinccwbs@aol.com) please let Mann Properties know you have done so.**